

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

	Type	Hits	Search Text	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on
1	BRS	369	sublimat\$3 near9 (glass fiber)	USPAT; US-PGPUB	2003/06/18 19:44		
2	BRS	433	(laser\$1 same beam\$1 same (cleav\$4 cut\$4) near7 fiber\$1)	USPAT; US-PGPUB	2003/06/18 19:55		
3	BRS	146	(laser\$1 same beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)	USPAT	2003/06/18 19:57		
4	BRS	126	(laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)	USPAT	2003/06/18 19:57		
5	BRS	1	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and sublimat\$5	USPAT	2003/06/18 20:03		
6	BRS	1	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and sublimat\$5) and (fiber near7 (hold\$4 position\$4))	USPAT; US-PGPUB	2003/06/18 20:04		
7	BRS	52	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4))	USPAT; US-PGPUB	2003/06/18 20:04		
8	BRS	53	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove))	USPAT; US-PGPUB	2003/06/19 12:34		
9	BRS	12	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove))) and ((beam\$1 laser\$1) near7 (cleav\$4 cut\$4) near7 (ribbon (bundle near1 fiber) fibers))	USPAT; US-PGPUB	2003/06/19 12:21		
10	BRS	12	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove))) and ((beam\$1 laser\$1) near7 (cleav\$4 cut\$4) near7 (ribbon (bundle near1 fiber) fibers))	USPAT; US-PGPUB	2003/06/19 12:27		
11	BRS	2	((laser\$1 near7 beam\$1 near7 (cleav\$4 cut\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove))) and ((beam\$1 laser\$1) near7 (cleav\$4 cut\$4) near7 (ribbon (bundle near1 fiber) fibers))) and cleav\$3	USPAT; US-PGPUB	2003/06/19 12:27		
12	BRS	5	((laser\$1 near7 beam\$1 near7 (cleav\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove))	USPAT; EPO; JPO; DERWENT	2003/06/19 12:41		

	Er ro rs
1	0
2	0
3	0
4	0
5	0
6	0
7	0
8	0
9	0
10	0
11	0
12	0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
13	BRS	6	((laser\$1 near5 beam\$1) near7 (cleav\$4) near7 fiber)) and (fiber\$1 same (hold\$4 position\$4 groove))	USPAT; EPO; JPO; DERWENT	2003/06/19 12:46		
14	BRS	4	((laser\$1 near5 beam\$1) near7 (cleav\$4) near7 fiber)) and (fiber\$1 same (hold\$4 position\$4 groove))) not ((laser\$1 near7 beam\$1 near7 (cleav\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove)))	USPAT; EPO; JPO; DERWENT	2003/06/19 12:44		
15	BRS	10	((laser\$1 near5 beam\$1) near7 (cleav\$4) near7 fiber))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:49		
16	BRS	4	((laser\$1 near5 beam\$1) near7 (cleav\$4) near7 fiber))) not (((laser\$1 near5 beam\$1) near7 (cleav\$4) near7 fiber)) and (fiber\$1 same (hold\$4 position\$4 groove))) not ((laser\$1 near7 beam\$1 near7 (cleav\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove))) (((laser\$1 near5 beam\$1) near7 (cleav\$4) near7 fiber)) and (fiber\$1 same (hold\$4 position\$4 groove))) ((laser\$1 near7 beam\$1 near7 (cleav\$4) near7 fiber\$1)) and (fiber near7 (hold\$4 position\$4 groove)))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:48		
17	BRS	0	((laser\$1 near5 beam\$1) near7 (cuting) near7 fiber)) and cleav\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:51		
18	BRS	0	((laser\$1 near5 beam\$1) near7 (cuting) near7 fiber))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:51		
19	BRS	75	((laser\$1 near5 beam\$1) near7 (cutting) near7 fiber))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:54		
20	BRS	2	((laser\$1 near5 beam\$1) near7 (cutting) near7 fiber))) and cleav\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:52		
21	BRS	94	laser\$1 same (beam\$1 near7 (cutting cleaving) near7 fiber\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 12:58		
22	BRS	86	laser\$1 same (beam\$1 near7 (cutting cleaving) near7 fiber\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 13:01		
23	BRS	1	(laser\$1 same (beam\$1 near7 (cutting cleaving) near7 fiber\$1)) and cleav\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 13:02		

	Er ro rs
13	0
14	0
15	0
16	0
17	0
18	0
19	0
20	0
21	0
22	0
23	0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
24	BRS	64	laser\$1 same (beam\$1 near9 (cutting cleaving) near2 fiber\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 19:53		
25	BRS	3	(laser\$1 same (beam\$1 near9 (cutting cleaving) near2 fiber\$1)) and cleav\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 13:05		
26	BRS	6	("4158555" "5226101" "5983676").pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 15:29		
27	BRS	3	((("4158555" "5226101" "5983676").pn.) and (laser same (cut\$3 chop\$4) near5 fiber\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 13:12		
28	BRS	278	(laser near5 (cut\$3 chop\$4 cleav\$3) near5 fiber\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 13:13		
29	BRS	254	(laser near5 (cutting chopping cleav\$3) near5 fiber\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/06/19 13:13		
30	BRS	224	(laser near5 (cutting chopping cleav\$3) near5 fiber\$1)	USPAT; EPO; JPO; DERWENT	2003/06/19 13:14		
31	BRS	128	(laser near5 (cutting chopping cleav\$3) near2 fiber\$1)	USPAT; EPO; JPO; DERWENT	2003/06/19 19:52		
32	BRS	20	"0097618"	EPO; DERWENT	2003/06/19 13:47		
33	BRS	0	"0097618"	EPO	2003/06/19 13:47		
34	BRS	0	"0097618" and laser\$1	EPO; DERWENT	2003/06/19 13:48		
35	BRS	1	seiler and zurcher	EPO; DERWENT	2003/06/19 13:49		
36	BRS	0	6087624.pn. and (fiber\$1 near7 (hold\$4 groov\$3 fix\$4 position\$3))	USPAT; US-PGPUB	2003/06/19 18:53		
37	BRS	0	6087624.pn. and (hold\$4 groov\$3 fix\$4 position\$3)	USPAT; US-PGPUB	2003/06/19 16:11		
38	BRS	1	6087624.pn.	USPAT; US-PGPUB	2003/06/19 16:23		
39	BRS	1213	6087624.pn. ((power laser beam\$3 volt\$1 amp\$3) near7 cut\$4 near7 (glass fiber\$1))	USPAT; US-PGPUB	2003/06/19 16:44		
40	BRS	1	6087624.pn. and ((power laser beam\$3 volt\$1 amp\$3) near7 cut\$4 near7 (glass fiber\$1))	USPAT; US-PGPUB	2003/06/19 17:00		
41	BRS	0	6087624.pn. and (mov\$4 same fiber\$1 same cut\$4) and (melt\$3 temperat\$4 degree\$1 heat\$4 therm\$5 sublim\$4)	USPAT; US-PGPUB	2003/06/19 17:40		
42	BRS	1	6087624.pn. and (mov\$4 same fiber\$1 same2 cut\$4) and (melt\$3 temperat\$4 degree\$1 heat\$4 therm\$5 sublim\$4)	USPAT; US-PGPUB	2003/06/19 17:19		
43	BRS	1	6087624.pn. and (laser\$1 beam\$1 path\$1 direction\$1 mov\$3 propel\$4 contol\$4)	USPAT; US-PGPUB	2003/06/19 17:20		

	Er ro rs
24	0
25	0
26	0
27	0
28	0
29	0
30	0
31	0
32	0
33	0
34	0
35	0
36	0
37	0
38	0
39	0
40	0
41	0
42	0
43	0

	Type	Hits	Search Text	DBs	Time Stamp	Corr mm en ts	Er ro r De fi ni ti on
44	BRS	1	6087624.pn. and (power energ\$3 burn\$4 melt\$3 temperat\$4 degree\$1 heat\$4 therm\$5 sublim\$4)	USPAT; US-PGPUB	2003/06/19 17:41		
45	BRS	1	6087624.pn. and (fibers near7 cut\$4)	USPAT; US-PGPUB	2003/06/19 18:58		
46	BRS	0	6087624.pn. and (laser near7 carbon\$6)	USPAT; US-PGPUB	2003/06/20 16:39		
47	BRS	1	"5430590"	JPO; DERWENT	2003/06/20 16:41		
48	BRS	6	"30590"	JPO; DERWENT	2003/06/20 16:42		

	Er ro rs
44	0
45	0
46	0
47	0
48	0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	L1	74	laser\$1 same (beam\$1 near9 (cutting cleaving) near2 fiber\$1)	USPAT; US-PGPU B; EPO; JPO; DERWENT	2004/02/23 13:19		
2	BRS	L2	184	laser\$1 same (beam\$1 near9 (cut\$4 cleav\$5 sublimit\$4) near2 fiber\$1)	USPAT; US-PGPU B; EPO; JPO; DERWENT	2004/02/23 13:20		

	Errors
1	0
2	0